

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

GW992  
NW  
> 1  
1.302 mi.  
6876 ft.

24 AVE / BATH AVE  
24 AVE / BATH AVE  
BROOKLYN, NY

NY Spills S106866565  
N/A

Site 3 of 3 in cluster GW

Relative:  
Higher

Actual:  
11 ft.

SPILLS:

Name: 24 AVE / BATH AVE  
Address: 24 AVE / BATH AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0412111 / 2005-06-07  
Facility ID: 0412111  
Facility Type: ER  
DER Facility ID: 272820  
Site ID: 337481  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2005-02-13  
Investigator: GDBREEN  
Referred To: Not reported  
Reported to Dept: 2005-02-13  
CID: 64  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2005-02-14  
Spill Record Last Update: 2005-06-07  
Spiller Name: Not reported  
Spiller Company: UNKNOWN  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: ERT DESK  
DEC Memo: "157208. 2/13/2005 02:45 HRS. J. GUARNERI #78261, SR. FIELD OPERATOR WITH F.O.D., REPORTS ON LOCATION INVESTIGATING ALIVE-ON-BACKFEED CONDITION ON FEEDER 7B43 (ACCT # C7160) AND AT 02:35 HRS. FOUND APPROX. 5 GAL UNKNOWN OIL ON TOP OF MUD ON FLOOR OF VS-5358. SPILL APPEARS TO BE CONTAINED. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. NO PRIVATE PROPERTY AFFECTED. NO SEWERS OR WATERWAYS AFFECTED. ENV. STOP TAG # 42416 PLACED. LIQUID SAMPLE TAKEN ON E PRIORITY TURNAROUND. CHAIN OF CUSTODY FORM # DD-03551 MARKED FOR 24-HOUR DEMINIMIS. CLEANUP PENDING TRANSFOMER BEING PRESSURE TESTED BY EQUIPMENT GROUP AND ALSO PENDING PCB RESULTS FROM CHEM LAB. -- W. WAINWRIGHT #17344 -- UPDATE 2/13/05 04:00 HRS -- TRANSFORMER INFORMATION FROM ECC WAREHOUSE: Serial ID: NBV600159, MFG Code: WE, KVA: 500, Mfr Date 12/01/1970, Install Date: 01/01/1971. HISTORICAL PCB RESULTS: SAMPLE DATE: 02/16/1997, PPM: 19, LAB SEQ # 97-01910. 2/13/05 0657HRS LAB RESULT RETURNED 18 PPM LSN-05-01230-001  
=====G  
DONATONE===== UPDATE: 2/13/05 - 1615. R. CILENTO - ENV. OPS., REPORTS TRANSFORMER FAILED PRESSURE TEST. FDR 7B43 IS PRESENTLY OFF THE SYSTEM FOR STATION WORK. MR. CILENTO BLOCKED OPEN THE UNIT AND REMOVED FUSES & DISCONNECTS. AN ASTORIA

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

TANKER HAS BEEN ORDERED TO DRAIN THE TRANSFORMER AND AN INITIAL CLEANUP WILL BE DONE BY ENV. OPS. THE UNIT WILL NOT BE REMOVED UNTIL 7B43 IS READY FOR FIELD WORK. THAT WILL NOT BE FOR ANOTHER 3 DAYS. THIS INCIDENT, THEREFORE, IS NOW OFF THE 24 HR CLOCK. TJ - 50495  
UPDATE 13-FEB-2005 20:47 HRS. BQ&E DEPT. SPLICER R.CILENTO EMP# 44214 REPORTS: UNIT CAPACITY LISTED AS 307 GALS. REMOVED 290 GALS OF LIQUID FROM UNIT WITH ASTORIA TANKER. THERE ARE 12 GALS OF DIELECTRIC FLUID UNACCOUNTED FOR. SPILL QUAINLY REMAINS AT 5 GALS. UPDATE 13-FEB-2005 19:15 HRS, ENVIR. OPER. MECH-A S.ROSENKING EMP# 61951 REPORTS: STARTED PRELIMINARY CLEANUP: DBL-WASHED STRUCTURE WITH BIO-GEN 760. SUMP THAT WAS EARLIER OPEN TO CHECK FOR SIGNS OF OIL WAS RESEALED. NO SIGNS OF OIL FOUND. ENVIR. TAG WILL REMAIN IN PLACE PENDING UNIT REMOVAL. 2-23-05 21:35HRS C. LUGO (ENV OPS) REPORTS, UNIT WAS REMOVED, HE DOUBLE WASHED STRUCTURE FIRST USING COAGULANT AND FOUND SUMP CEMENTED. TAG WAS REMOVED AND JOB 100 COMPLETED."

Remarks:

"No to 5 questions. #157208."

All Materials:

Site ID: 337481  
Operable Unit ID: 1099431  
Operable Unit: 01  
Material ID: 579778  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 4.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported